

Service Note - 22003 Regarding MES1001 NOx Sensor

Date: 03-06-2022

**Danfoss IXA A/S
Service & Support**
www.danfoss-ixa.com

Address
Marsvej 5
DK-6000 Kolding
Contact
ixa.service@danfoss.com
+45 7488 8500

Dear Customer.

At Danfoss IXA our products are subjects to continuous development and updates. We strive to keep our customers informed regarding these developments and updates hence we send you this Service Note for MES1001. Kindly read the below information.

MES 1001/MES 1001 MARPOL Software Update

MES 1001 and MES 1001 MARPOL has received a software update to SW revision 5.1.11.2. Instructions on how to update the MES1001/MES1001 MARPOL are described in section 2.4.2 *Updating Software* in the User Guide for MES1001 and MES 1001 MARPOL respectively. SW revision 5.1.11.2 includes following updates:

- Fixed issue which could make the sensor crash when updating it with revision 5.1.10 and 5.1.10.1 through the USB interface (**IMPORTANT: Revisions 5.1.10 and 5.1.10.1 must not be used for update through USB**)
- Fixed issue with low input pressure alarm delay being too short.

We recommend all customers to update their MES 1001 or MES1001 MARPOL with this new software revision as it contains valuable improvements.

Previous Service Notes can be found at <https://danfoss-ixa.com/services-and-support>.

Best regards,
Service & Support

ixa.service@danfoss.com

Debnath Mandal
Service and Support Manager

03-06-2022