

Service Note – 22006

Regarding MES1003 Washwater Monitoring System

Date: 14-10-2022

Danfoss IXA A/S
Service & Support
www.danfoss-ixa.com

Address
Marsvej 5
DK-6000 Kolding
Contact
ixa.service@danfoss.com
+45 7488 8500

Dear Customer.

At Danfoss IXA our products are subjects to continuous development and updates. We strive to keep our customers informed regarding these developments and updates hence we send you this Service Note for MES1003. Kindly read the below information.

Updated MES1003 Software version 1.2.7

MES1003 has received a software update to SW version 1.2.7. The software update can be downloaded at <https://danfoss-ixa.com/services-and-support>. Instructions on how to update the MES1003 is described in section 2.3.2 *Updating Software* in the User Guide for MES1003.

SW version 1.2.7 includes following new changes and/or functionalities:

- PAHphe reading is now available from Modbus interface
- Fixed support and service address being wrong in the LCP
- Added LCP menu item to choose PAH or PAHphe to be displayed
- Fixed issue where wrong return code was returned when starting the system
- Modbus
 - Added coil to activate local control
 - Added coil to show status of local control
 - Added Enable / disable local control mode from LCP

Previous Service Notes can be found at <https://danfoss-ixa.com/services-and-support>.

Best regards,
Service & Support
ixa.service@danfoss.com

Prepared:

Debnath Mandal
Service and Support Manager

14-10-2022

Classified as Business